

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
					1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	W	I	K	N	P	1	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT

0	1	L	0	5	0	0	0	3	0	5	0	5	1	6	8	1	0	6	1	5	8	1			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During the performance of surveillance testing it was discovered that two pressurizer pressure transmitters had drifted, causing the high pressure reactor trip setpoint for those transmitters to be 1 psig and 5.6 psig above Tech. Spec. limits respectively. The remaining channel was within Tech. Spec. limits. If required the high pressure reactor trip would not have occurred within the limits of Technical Specification TS 2.3.a.2.A.

0	9	I	A	X	Z	I	N	S	T	R	U	T	Z	8	1	0	1	7	0	3	L	0	E	Z	Z	Z	0	0	0	0	N	N	N	F	1	8	0			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE LER/RO REPORT NUMBER EVENT YEAR SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The cause of both instruments being out of specification was determined to be instrument drift. Both instruments were recalibrated and brought within specifications. A document review has shown these instruments to be reliable in the past. No failures were found and no further action is deemed necessary at this time.

1	5	H	0	0	0	NA	B	Surveillance Testing	0	0	0	NA	0	0	0	NA	0	0	0	NA	Z	NA
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION PERSONNEL INJURIES NUMBER DESCRIPTION LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION PUBLICITY ISSUED DESCRIPTION8107160242 810412
PDR ADOCK 05000305
S PDR

NRC USE ONLY

NAME OF PREPARER

D. J. Molzahn

JUN 15 1981

PHONE

(414) 388-2560