

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

I L D R S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 50

REPORT SOURCE L 6 0 5 0 0 0 2 3 7 7 0 6 0 9 8 1 8 0 7 0 7 8 1 9

80 81 DOCKET NUMBER 88 89 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During suppression chamber to drywell vacuum breaker operability test, DOS 1600-9, vacuum breaker 2-1601-32C was found binding. It was chained closed per T.S. 3.7.A.4.b. Public health and safety was not jeopardized since 2-1601-32C was closed prior to surveillance, and 11 of the 12 vacuum breakers were still operable (9 required). Last previous event: R.O. 50-237/79-64.

SYSTEM CODE S A 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE C 15 VALVE SUBCODE C 16

17 LER/RO REPORT NUMBER 8 1 EVENT YEAR 8 1 SEQUENTIAL REPORT NO. 0 3 8 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

ACTION TAKEN E 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 22 NPRO-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER A 5 8 5 26

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The cause of the binding was improper clearance on the shaft seals. The seals were adjusted and tested satisfactorily. DOS-1600-9 will continue to be run monthly.

FACILITY STATUS E 28 % POWER 0 4 5 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Routine Surveillance 32

ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY DESCRIPTION N/A 45

ISSUED N 44

8107200058 810708
PDR ADOCK 05000237
S PDR

NAME OF PREPARER

K. Zirwas

PHONE

942-2920 Ext. 422

NRC USE ONLY

P.O. 917-926



Commonwealth Edison

DEVIATION REPORT

DVR NO. STA UNIT YEAR NO.
D-12 - 2 - 81 - 62

PART 1 TITLE OF DEVIATION		OCCURRED	
Vacuum Breaker 1601-32C Binding		6/9/81	1
SYSTEM AFFECTED 1600		DATE	TIME
Primary Containment		TESTING	
PLANT CONDITIONS		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
MODE Run	PWR (MWT) 1150.6	LOAD (MWE) 318.9	

DESCRIPTION OF EVENT
During suppression chamber to drywell vacuum breaker operability test, DOS 1600-2, vacuum breaker 2-1601-32C was binding. Checked shaft seals, greased, no change.

DESCRIPTION OF CAUSE
Unknown

OTHER APPLICABLE INFORMATION
Vacuum breaker chained closed.

EQUIPMENT <input checked="" type="checkbox"/> YES FAILURE <input type="checkbox"/> NO	DR NO. N/A	WR NO. 14115	R. Weidner RESPONSIBLE SUPERVISOR	6/9/81 DATE
--	---------------	-----------------	--------------------------------------	----------------

PART 2 OPERATING ENGINEERS COMMENTS
The remaining vacuum breakers were operable. The vacuum breaker will be repaired during the next unit outage.

TYPE OF DEVIATION REPORTABLE OCCURRENCE	EVENT OF POTENTIAL PUBLIC INTEREST	TECH SPEC VIOLATION	NON-REPORTABLE OCCURRENCE	ANNUAL REPORTING	SAFETY-RELATED WR ISSUED
<input type="checkbox"/> 14 DAY <input type="checkbox"/> 10CFR21	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
<input checked="" type="checkbox"/> 30 DAY NOTIFICATION 6.6.B.2.5					

REPORTABLE OCCURRENCE NUMBER	ACTION ITEM NO.	PROMPT ON-SITE NOTIFICATION
81-38/03L-0		R. M. Ragan
		TITLE
		DATE
		TIME

24-HOUR NRC NOTIFICATION (Courtesy)	PROMPT OFF-SITE NOTIFICATION
<input checked="" type="checkbox"/> TPH Mike Jordan 6/9/81 1200 hrs	F. A. Palmer
REGION III DATE TIME	TITLE
	DATE
	TIME
<input type="checkbox"/> TGM REGION III & DOL DATE TIME	
	TITLE
	DATE
	TIME

RESPONSIBLE COMPANY OFFICER INFORMED OF 10CFR21 CONDITIONS AND THEIR REPORT TO NRC

REVIEW AND COMPLETED John Wuiciga OPERATING ENGINEER 6/12/81 DATE

ACCEPTANCE BY STATION REVIEW AS REQUIRED

DATE

RESOLUTION APPROVED AND AUTHORIZED FOR DISTRIBUTION

John Wuiciga John Wuiciga
7-7-81 7/7/81
Douglas Sweet 7/7/81
STATION SUPERINTENDENT DATE