



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

OMB/LEP

June 16, 1981

DJS LTR #81-409



James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #81-05/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation. The reason for the revision is to update the cause description and corrective actions taken and future action portions of the Licensee Event Report.

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/lg

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Mgt. Branch
File/NRC

*IE22
5
1/1*

8107200226 810616
PDR ADOCK 05000237
S PDR

JUL 14 1981



Commonwealth Edison

DEVIATION REPORT

Revision #1

DVR NO.	STA	UNIT	YEAR	NO.
D-12	-	2	-	81-6

RT 1 TITLE OF DEVIATION

Failure of 2-1601-23 Valve to Pass LLRT

OCCURRED

1-17-81

1100

DATE

TIME

SYSTEM AFFECTED 1600

PLANT CONDITIONS

Pressure Suppression

MODE Shutdown

PWR (M) 0

LOAD (MWE) 0

TESTING

☒ YES ☐ NO

DESCRIPTION OF EVENT

During LLRT of Drywell and torus vent, 2-1601-23 valve failed to hold pressure. Leak Rate determined to be 1715.55 SCFH

DESCRIPTION OF CAUSE

Unknown at this time

OTHER APPLICABLE INFORMATION

Reactor in cold shutdown Primary Containment not required.

EQUIPMENT ☒ YES
FAILURE ☐ NODR NO.
N/AWR NO.
D11279

K. R. Zirwas

RESPONSIBLE SUPERVISOR

1-17-81

DATE

PART 2 OPERATING ENGINEERS COMMENTS

The measured leakage exceeded the limit for a single isolation valve (29.38 SCFH, T.S. 4.7.A).

a leakage was determined to be through the 2-1601-23 valve toward the drywell.

TYPE OF DEVIATION
REPORTABLE OCCURRENCE☐ 14 DAY ☐ 10CFR21☒ 30 DAY NOTIFICATION
6.6.B.2.bEVENT OF POTENTIAL
PUBLIC INTEREST☐TECH SPEC
VIOLATION☐NON-REPORTABLE
OCCURRENCE☐ANNUAL
REPORTINGYES ☒NO ☐SAFETY-
RELATED
WR ISSUEDYES ☒NO ☐REPORTABLE OCCURRENCE
NUMBER

81-05/03X-1

ACTION ITEM NO.

PROMPT ON-SITE NOTIFICATION

R. M. Ragan

1/22/81

1200

TITLE

DATE

TIME

TITLE

DATE

TIME

24-HOUR NRC NOTIFICATION

☐ TPH N/A

REGION III

DATE

TIME

☐ TGM N/A

REGION III & COL

DATE

TIME

PROMPT OFF-SITE NOTIFICATION

F. A. Palmer

1/22/81

1:33

TITLE

DATE

TIME

TITLE

DATE

TIME

RESPONSIBLE COMPANY OFFICER INFORMED OF 10CFR21
CONDITIONS AND THEIR REPORT TO NRC

TITLE

DATE

TIME

REVIEW AND COMPLETED

John W. Wujciga

OPERATING ENGINEER

1/20/81

DATE

ACCEPTANCE BY STATION REVIEW
AS REQUIRED

DATE See Supplemental DVR
Cover Sheet for signatures
RESOLUTION APPROVED AND
AUTHORIZED FOR DISTRIBUTION

STATION SUPERINTENDENT

DATE