

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C M G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
 01
 7 8
 REPORT SOURCE L 5 0 5 0 0 10 3 6 9 7 0 4 1 2 8 1 3 0 5 1 2 8 1 9
 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
 02 While in Mode 3, initial fuel loading, Train A of the Solid State
 03 Protection System was declared inoperable because several erroneous
 04 permissive block indications appeared on the Control Room Status
 05 Panel. This is in violation of T.S.3.3.2 and required implementation
 06 of the appropriate Action Statement as stated in T.S. Table 3.3-3.
 07 Since a fully redundant train was still operable, the health and
 08 safety of the public were not affected.

09
 7 8 9
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 I A 11 E 12 A 13 I N S T R U 14 X 15 Z 16
 9 10 11 12 13 14 15 16 17 18 19 20
 17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 8 1 0 9 1 0 3 L 0
 21 22 23 24 25 26 27 28 29 30 31 32
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPROH FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
 A 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 L 25 W 1 2 0
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
 10 Two circuit boards were found to be defective due to
 11 temperature related degradation. The defective circuit
 12 boards were replaced and the system was returned to
 13 service.

14
 7 8 9
 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
 X 28 0 0 0 C 29 Mode 3 A 31 Operator Observation
 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
 Z 33 Z 34 NA NA
 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
 0 0 0 37 Z 38 NA
 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 PERSONNEL INJURIES NUMBER DESCRIPTION
 0 0 0 40 NA
 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
 Z 43 NA
 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 PUBLICITY ISSUED DESCRIPTION
 N 44 NA
 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 NAME OF PREPARER R. W. Ouellette
 PHONE (704) 373-7530
 NRC USE ONLY

8107200392 810512
PDR ADCK 05000369
S PDR