

**Detroit
Edison**

Donald A. Wells
Manager, Quality Assurance
(313) 237-9657
2000 Second Avenue
Detroit, Michigan 48226
(313) 237-8000

June 24, 1981
EF2-53561

Mr. G. Fiorelli, Chief
Reactor Construction and Engineering
Support Branch
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Noncompliance at Enrico Fermi Unit 2 Construction Site

Dear Mr. Fiorelli:


This letter responds to the items of noncompliance contained in your IE Report 50-341/81-04. This inspection of Enrico Fermi Unit 2 Site Construction activities was performed by Mr. I.T. Yin of NRC Region III on April 21-24, 1981.

Only the cited item of noncompliance is discussed in this reply, as required by Section 2.201 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations. The unresolved items have been acted upon and we will be prepared to discuss this action with your inspectors on their next visit.

The enclosed response is arranged in sequence of items cited in the body of your report. The finding and section numbers are referenced.

We trust this letter satisfactorily answers the concerns raised in your report. We shall be glad to discuss any further concerns you may have.

Very truly yours,



DAW/HAW/cp

Mr. G. Fiorelli, Chief
Page Two

June 24, 1981
EF2-53561

cc: Mr. Victor Stello, Jr. Director
Office of Inspection and Enforcement
Division of Reactor Inspection Programs
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Bruce Little, Resident Inspector
U.S. Nuclear Regulatory Commission
Resident Inspectors Office
6450 North Dixie Highway
Newport, Michigan 48166

THE DETROIT EDISON COMPANY
QUALITY ASSURANCE DEPARTMENT
ENRICO FERMI 2 PROJECT

Response to NRC Report No. 50-341/81-04

Docket No. 50-341 License No. CPPR-87

Inspection at: Fermi 2 Site, Monroe, Michigan

Inspection conducted: April 21-24, 1981

Prepared by:

H. A. Walker

H.A. Walker, Supervisor
Construction Quality Assurance

Approved by:

T. A. Alessi

T.A. Alessi, Director
Project Quality Assurance

Response to NRC Inspection Report # 50-341/81-04

Statement of Violation 81-04, Appendix A, (81-04-01)

Contrary to the requirements of 10CFR50, Appendix B, Criterion VI a site contractor at the Enrico Fermi, Unit 2 site used an inter-office memorandum to document changes to procedures and as a result by-passed the established document control procedures.

Corrective Action Taken and the Results Achieved

Administrative Procedure AP-IV-20, Revision 0, entitled, "Disassembling and Re-Assembling of Pipe, Conduit and Cable Tray Support" has been prepared, approved and was issued for use on May 5, 1981. This procedure incorporates the methods described in memorandum DIC 81-0284, DIC 81-0965 and DIC 81-1543 which are noted in item 2 on page 4 of the Inspection Report.

Corrective Action Taken to Avoid Further Noncompliance

Enrico Fermi 2 site organizations have been notified of the problem. They were cautioned to review all letters and memorandums originated by the respective organizations for this problem. Construction Quality Assurance personnel have been notified to review incoming correspondence for this problem.

Date When Full Compliance Will Be Achieved

All required action has now been completed.

The foregoing statements are based on facts
and circumstances which are true and accurate
to the best of my knowledge and belief.

H.A. Walker

H.A. Walker, Supervisor
Construction Quality Assurance

Subscribed and sworn

to before me this

24th day

of June, 1981.

Jennifie Kyko

JENNIFIE KYKO
Notary Public, Monroe County, MI
My Commission Expires Nov. 25, 1984