

LER #: 50-321/1981-061
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-321

Narrative Report
for LER 50-321/1981-061

On 6-29-81, while the plant was in steady state operation at 2400 MWt and while performing HNP-1-3604, GE H₂ Analyzer Calibration, analyzer N62-N009A was found out of calibration, and N62-N009B was found inoperative. The event date is unknown but was reported inoperative on 6-29-81. Tech Specs table 2.1.3.h, page 2-7, requires one operable channel. Plant operation was not affected as a result of this event. The health and safety of the public was not affected. This is a repetitive event as last reported on LER 50-321/1981-056.

The cause of this event is presently unknown. MR 1-81-5048 has been issued to correct the problem. An update report will be submitted.

A generic review revealed no inherent problems.