

ILLINOIS POWER COMPANY



1605-L
U-0254
L14-81(07-09)-L
500 SOUTH 27TH STREET, DECATUR, ILLINOIS 62525

July 9, 1981

DMB/RE
50.55

Mr. James G. Keppler
Director Region III
Office of Inspection and Enforcement
U.S. Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137




Dear Mr. Keppler,

Deficiency 80-09
10 CFR 50.55(e)
Inadequate Construction Controls
Concerning Electrical Raceway
Hanger Installation

Please reference my letter U-0231, L14-81(05-06)-L dated May 6, 1981 concerning progress in corrective action associated with the electrical hanger installation at Clinton Power Station. Since my last letter, we have issued and implemented procedures for the drafting and review of as-built drawings, defined the construction to ensure that travelers are developed for each hanger, and ensured that changes are made to travelers only after an engineering approval. In addition, we are continuing the development and implementation of the computer tracking system which will ensure that affecting documents (i.e., ECN's, FCR's, etc.) are listed and incorporated as applicable.

We expect to submit a final report on this matter by the end of August 1981.

Sincerely,


L.J. Koch
Vice President

IE27
S
1/0

GWB/prh

cc: H.H. Livermore, NRC Resident Inspector
Director, Office of I&E, USNRC, Washington, DC 20013
Director-Quality Assurance