

OFFICIAL COPY

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

July 10, 1981

TELEPHONE: AREA 704  
373-4083

Mr. J. P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/81-99 was to have been submitted by July 10, 1981. This 30-day reportable occurrence concerns Technical Specification 3.3.3.8, "The radioactive liquid effluent monitoring instrumentation channels shown in Table 3.3-12 shall be operable with their alarm/trip setpoints set to ensure that the limits of Specification 3.11.1.1 are not exceeded," which was violated on June 10, 1981. At this time, all of the required information is not yet available. The complete report will be submitted by August 10, 1981.

Very truly yours,

*William O Parker Jr. by WAA*  
William O. Parker, Jr.

PBN:scs  
Attachment

cc: Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
P. O. Box 10412  
Palo Alto, California 94303

Ms. M. J. Graham, NRC Resident Inspector  
McGuire Nuclear Station

IE22  
S  
I/O