

CONTROL BLOCK.

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	V	A	S	P	S	7	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
LICENSEE CODE						LICENSEE NUMBER														LICENSE TYPE					CAT		

CONT.

REPORT SOURCE L 6 0 5 0 0 0 2 R 0 7 0 7 0 9 8 1 8 9
60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | With the Unit at 42% power TE-1-422D Delta T protection indicated zero. The bistables
0 3 | were placed in trip and the Technicians began investigation. In order to assist in
0 4 | the performance of PT 8.5 the Technician returned the Delta T bistables to normal
0 5 | with the TE-1-422D still indicating zero Delta T. This is contrary to a degree of
0 6 | redundancy requirement of T.S. 3.7 Table 3.7.1 and is reportable in accordance with
0 7 | T.S. 6.6.2.a(2)

0 9

SYSTEM CODE 11 I A 12

CAUSE CODE 12 A 13

CAUSE SUBCODE 13 C 14

COMPONENT CODE 14 I N S T R U 15

COMP SUBCODE 15 X 16

VALVE SUBCODE 16 2 17

LEAKED REPORT NUMBER 17 8 1 18

EVENT YEAR 18 8 1 19

SEQUENTIAL REPORT NO. 19 0 2 3 20

OCCURRENCE CODE 20 0 1 21

REPORT TYPE 21 I 22

REVISION NO. 22 0 23

ACTION TAKEN 23 24

FUTURE ACTION 24 25

EFFECT ON PLANT 25 26

SHUT/DOWN METHOD 26 27

HOURS 27 28

ATTACHMENT SUBMITTED 28 Y 29

APPROX FORM SAIL 29 30

PRIME COMP. SUPPLIER 30 31

COMPONENT MAINT. ACTUATOR 31 32

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

10	The bistables were returned to Trip. Further investigation revealed the Tc and Th
11	RTD's were wired incorrectly. Investigation is continuing.
12	
13	
14	

7 8 9
FACILITY STATUS 10 POWER 11 OTHER STATUS 12 METHOD OF DISCOVERY 13 DISCOVERY DESCRIPTION

1 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

7 8 9
ACTIVITY RELEASED 10 CONTENT 11 AMOUNT OF ACTIVITY 12 LOCATION OF RELEASE

1 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PERSONNEL EMPLOYERS
NUMBER TYPE DESCRIPTION


1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
										REGIONAL DIRECTOR																																																																																									
										DEPUTY DIRECTOR																																																																																									

PERSONNEL, SUPPLIES
NUMBER DESCRIPTION (41)

DIRECTOR, RHP
DIRECTOR, EPOS

DIRECTOR, ENF/INV

8107210310 810721

30 
 PDR ADDCK 05000280
 S PDR

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED
DATE 08-01-2001 BY 60322 UCBAW

100-441101-1000

J. L. Wilson

(804) 357-3184

NAME OF DONOR J. L. Wilson

(804) 357-3184