

50-483/486


UNION ELECTRIC COMPANY
1901 GRATIOT STREET
ST. LOUIS, MISSOURI

JOHN K. BRYAN
VICE PRESIDENT

July 13, 1981

MAILING ADDRESS:
P. O. BOX 149
ST. LOUIS, MISSOURI 63166

Mr. James G. Keppler, Director
USNRC Region III
799 Roosevelt Road
Glen Ellyn, IL 60137



ULNRC- 464

Dear Mr. Keppler:


INTERIM 10CFR50.55(e)/10CFR21 REPORT NO. U-25
CALLAWAY PLANT UNIT 1

The purpose of this letter is to update the reference report and the interim report, dated March 2, 1981 concerning weld discrepancies in the Main Control Panels and Auxiliary Relay Racks furnished to Callaway Unit 1 by Comsip Customline Corporation.

The planned inspection and measurement of the panel and rack welds have been completed and the results are presently being evaluated by the panel designer and by the architect-engineer. Preliminary results of these evaluations appear to confirm the adequacy of the panel and rack welds.

We presently anticipate the evaluation will be complete on or about November 30, 1981. A report summarizing the results of the inspections and evaluation will be forwarded to the NRC shortly thereafter.

Very truly yours,


John K. Bryan

MHH/jds

cc: J. Konklin, Region III
B. H. Grier, Region I
Victor Stello, Jr., Director I&E
W. A. Hansen, NRC Resident Inspector, Callaway Plant
Missouri Public Service Commission

IE27
S
1/0

8107240024 810713
PDR ADOCK 05000483
S PDR

JUL 17 1981