



DMB/LER

Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

July 17, 1981



Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-306 License No. DPR-60

Failure of the No. 21 RCP Shaft

The Licensee Event Report for this occurrence is produced on the back of this letter. Enclosed are three copies. This event was reported to you via phone/telecopy on July 6, 1981/July 7, 1981.

This event is reported for your information.

for Thomas Parker

L O Mayer, PE
Manager of Nuclear Support Services

LOM/TMP/bd

cc: Director, IE, USNRC (3)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

IE22
5
1/1

-over-