

June 18, 1981

File: NG-3513(R)

Serial No.: NO-81-1036

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
SUPPLEMENTAL RESPONSE TO BULLETIN 80-21
VALVE COMPONENTS SUPPLIED BY MALCOLM FOUNDRY COMPANY, INC.

Dear Mr. O'Reilly:

Carolina Power & Light Company's original response to IE Bulletin 80-21 stated that no active safety related valves in use at H. B. Robinson, Unit No. 2 had yokes manufactured by Malcolm Foundry Company, Inc. The Bulletin, however, asked a more generic question concerning all valve parts cast by Malcolm. Therefore, Carolina Power & Light Company is supplementing its original response to IE Bulletin 80-21 with the following additional information. There are no active safety related valves in use at H. B. Robinson, Unit No. 2 which have any components cast by Malcolm Foundry Company, Inc.

If you have any additional questions concerning this information, please contact me or a member of my staff.

Yours very truly,



B. J. Furr
Vice President
Nuclear Operations

FMG/jc (2296)

cc: Mr. James H. Sniezek



IE11
s
1/0

8107240493 810618
PDR ADDCK 05000261
Q PDR