

400 Chestnut Street Tower II

June 15, 1981

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-20 -RII:JPO 50-518,
-519, -520, -521, -553, -554 - HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS

Our initial response to the subject bulletin, was submitted on September 12, 1980, followed by our second interim response on February 10, 1981. This letter constitutes TVA's third interim response to the subject bulletin.

TVA is continuing to work with Westinghouse on resolution of the concern on W-2 switches. We have asked Westinghouse to keep us informed of the progress of the fatigue failure test program for the W-2 switches. In addition, we have requested Westinghouse to keep us informed of their long-term resolution to the W-2 switch problem. GE is still in the process of collecting the requested information. TVA anticipates transmitting the final report on or before August 14, 1981. If you have any questions, please call Jim Damer at FTS 857-2014.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Division of Reactor Operations Inspection
Washington, DC 20555



8107240520 810615
PDR ADDCK 05000518
Q PDR