

FOR DCS PROCESSING  
Original document not available  
to NRC  
Certified by *D. Wack*

*Southern California Edison Company*

P. O. BOX 800  
2244 WALNUT GROVE AVENUE  
ROSEMEAD CALIFORNIA 91770

D. E. NUNN  
MANAGER, QUALITY ASSURANCE

June 23, 1981



TELEPHONE  
(213) 572-1695

Mr. R. H. Engelken, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region V  
Suite 202, Walnut Creek Plaza  
1990 North California Boulevard  
Walnut Creek, California 94506

Dear Mr. Engelken:


Subject: Docket Nos. 50-361 and 50-362  
San Onofre Nuclear Generating Station, Units 2 and 3

This letter confirms verbal notification on June 23, 1981 of a condition discovered in construction which is considered reportable in accordance with 10CFR-50.55(e). The condition involves improper assembly of coaxial connectors in electrical containment penetrations.

We are performing an evaluation of this condition and will submit an appropriate report in accordance with 10CFR50.55(e)(3). If you have any questions or require additional information, please let me know.

Very truly yours,

cc: R. J. Pate (NRC, San Onofre Units 2 and 3)  
Dr. L. T. Papay



*IE27*  
*S/10*

8107280238 810623  
PDR ADOCK 05006361  
S PDR