

1750 Chestnut Street Tower II

July 21, 1981

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRC-50-296/81031

The enclosed report provides details concerning the 3-A reactor recirculation
pump which tripped due to 2A-K45A relay action. This report is submitted
in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
A. J. Green

Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control

U.S. Nuclear Regulatory Commission

Washington, DC 20555

Director (40)

Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission

Washington, DC 20555

Mr. Bill Lavallee

Nuclear Safety Analysis Center

Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

IE22
5/11