

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	9	8	7	0	5	2	2	8	1	8	0	6	1	6	8	1	9
60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 As part of a follow-up inspection of an unexpected alarm, it was discovered that the

0 3 CS header break detection instrument switches were piped to the incorrect CS lines,

0 4 i.e., CS-DPIS-43A was connected to the B loop header and CS-DPIS-43B to the A loop

0 5 header. At the time of the discovery of the occurrence the CS systems were not re-

0 6 quired to be operable. This occurrence had no adverse affect on the public health

0 7 and safety. This event is not repetitive.

0	8											80										
0	9																					
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE										
S	F	11	B	12	C	13	I	N	S	T	R	U	14	I	15	Z	16					
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.														
8	1	0	1	1	0	3	I	0														
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP SUPPLIER		COMPONENT MANUFACTURER						
F	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	Z	24	Z	25	Z	9	9	9	26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																						

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this occurrence is that the instrument lines were connected to the

1 1 wrong line at the drywell penetration. To correct the problem, the instruments

1 2 were connected to the proper lines. No further action is planned.

1 3

1 4

FACILITY STATUS (28) H 0 0 0 (29) NA (30) OTHER STATUS
 METHOD OF DISCOVERY (31) C Operator Inspection (32) DISCOVERY DESCRIPTION
 ACTIVITY CONTENT (33) 2 (34) Z (35) NA AMOUNT OF ACTIVITY
 RELEASED OF RELEASE (36) NA LOCATION OF RELEASE

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	37	Z	38	NA		

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40 NA

LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION		(43)	
1	9	Z	(47)	NA			

ISSUED PUBLICITY (45) DESCRIPTION (44) NA