

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	T	N	S	N	P	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5							
LICENSEE CODE								14	LICENSE NUMBER										25	LICENSE TYPE								30	LIC. CAT. NO.					35

REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	Unit 1 in Mode 1 at 100% RTP. Ice condenser intermediate deck doors were found to
---	---	---

03 be frosted. This required entry into LCO 3.6.5.3. There was no effect upon public

0 4 | health or safety. Previous occurrences - 4. (Reference SQRO-50-327/81002, 80205,

$\boxed{0} \boxed{5}$ | 80203, and 80170).

0	6
---	---

07 _____

0 8 _____

7 8 9

0 9

SYSTEM CODE

S B (11)

9 10

CAUSE CODE

X (12)

11

CAUSE SUBCODE

Z (13)

12

COMP. SUBCODE

X (15)

19

VALVE SUBCODE

Z (16)

20

COMPONENT CODE

P E N E T R (14)

13 18

(17) LER/RO REPORT NUMBER 81 —

EVENT YEAR —

SEQUENTIAL REPORT NO. 073 /

OCCURRENCE CODE 03

REPORT TYPE L —

NO. 01

ACTION TAKEN: X (18) FUTURE ACTION: A (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0000 (22) ATTACHMENT SUBMITTED: N (23) NPRO-4 FORM SUB.: N (24) PRIME COMP. SUPPLIER: N (25) COMPONENT MANUFACTURER: W (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Due to damaged tape seals on the upper deck doors, moisture was dripping from the

1 1 | upper deck doors onto the intermediate deck doors. Frost was removed from the

by 6-30-81. The damaged tape seals will be replaced as soon as material is available.

113

1 4

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	1	0	0	NA			B	Surveillance test				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 2 33 3 34 NA

7 8 9 10 11 44

NA LOCATION OF RELEASE (36)

45

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION
1	7	000	17	Z	38 NA

PERSONNEL INJURIES

PERSONNEL		NUMBER		DESCRIPTION	
1	8	0	0	(11)	NA
LOSS OF OR DAMAGE TO FACILITY (12)					

19 2 42 NA
7 8 9 10
PRIORITY 45
8107280523 810720
RDR ADPCK 05000327
NRC USE ONLY

ISSUED DESCRIPTION PDR ADDRESS 000000 PDR

7 8 9 10 68 69

2 0 N NA

Name of Preparer: Glenn B. Kirk/M. R. Harding

Phone: (615) 842-8317