



LEL  
50-368/81-017/01T

ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

July 2, 1981

2CAN078102

Mr. G. L. Madsen, Chief  
Reactor Projects Branch  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



SUBJECT: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Report No. 81-017/01T-1  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.8.e, attached is the subject report concerning a failure of the Resistance Temperature Detectors (RTD's). This is a revision to a previous submittal dated May 20, 1981.

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:GAC:lp

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

Mr. Norman M. Haller, Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

8107280601 810702  
PDR ADOCK 050C0368  
S PDR

IE22  
S  
1/1