

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
LICENSEE CODE				LICENSE NUMBER												LICENSE TYPE				CAT 58						
CON'T		REPORT SOURCE		DOC. NUMBER												EVENT DATE				REPORT DATE						
0	1	L	6	0	5	0	0	0	3	6	6	7	0	6	3	0	8	1	8	0	7	2	1	8	1	9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

While Plant was at 2276 MWT, APRM surveillance HNP-2-3054 was not performed within the time limit as required. Tech. Specs. Section 4.3.1.1 requires HNP-2-3054 to be performed weekly within a certain time period as stated in Surveillance Manual. The health and safety of the public was not affected. This event is non-repetitive.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		ALVE SUBCODE	
I	A	A	A	A	Z	Z	Z	Z	Z	Z	R	Z	
11		12		13		14				15		16	
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
8	1	0	6	9	0	3	L	0					
21		22		23		24		25					
LER/RO REPORT NUMBER		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
H	Z	Z	Z	0	0	0	Y	N	Z	Z	9	9	9
33		34		35		36		37		38		39	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Personnel overlooked HNP-2-3054 in surveillance book. This was reported to the Shift Foreman. The Shift Foreman had personnel to perform HNP-2-3054 to complete the surveillance requirement.

FACILITY STATUS		POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
E	0	9	3	NA	B	Operator Observation			
28		29		30		31		32	
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
Z	Z	NA		NA					
33		34		35		36			
PERSONNEL EXPOSURES		DESCRIPTION							
0	0	0	NA						
37		38		39					
PERSONNEL INJURIES		DESCRIPTION							
0	0	0	NA						
40		41		42					
LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION							
Z	NA								
43		44		45					
PUBLICATION		DESCRIPTION							
N	NA								
46		47		48					
ISSUED		DESCRIPTION							
N	NA								
49		50		51					
NAME OF PREPARER		PHONE							
S. X. Baxley, Supt. Operations		912-367-7781							

8107310179 810721
PDR ADDCK 05000366
S PDR

NRC USE ONLY

LER #: 50-366/1981-069
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1981-069

Surveillance was overlooked by personnel on the evening shift of 6-30-81. Tech. Specs. section 4.3.1.1 requires HNP-2-3054 to be performed weekly. The date of 6-30-81 was the last day that HNP-2-3054 could be performed and still be within the weekly time period. This was discovered on 7-2-81 by the Shift Foreman on duty.

The personnel who overlooked this surveillance requirement has been instructed by his immediate supervisor as to the importance of HNP-2-3054 APRM Surveillance and as to how the surveillance manual can be kept up-to-date and current requirements performed within the proper time frames.