

TENNESSEE VALLEY AUTHORITY

OFFICIAL COPY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

June 30, 1981 JUL 7 4 8: 04

HTRD-50-518, -519, -520, -521/81-04
PBRD-50-553/81-06, -554/81-04

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - COMPLETION OF AS-BUILT
DRAWINGS - HTRD-50-518, -519, -520, -521/81-04 AND
PBRD-50-553/81-06, -554/81-04

The subject deficiencies were initially reported to NRC-OIE, Region II, Inspector R. W. Wright on January 22, 1981, as NCR's HTN-M80-10 and PBN-M80-10, deficiency Nos. 13, 14, and 21. The first and second interim reports were submitted on February 23 and April 1, 1981. In compliance with paragraph 50.55(e) of 10 CFR Part 50, this letter constitutes the third interim report on the subject deficiencies.

Corrective actions have been proposed by TVA and are being submitted to GE for concurrence. As a result, we anticipate transmitting an additional report on or before December 15, 1981. If you have any questions, please call Jim Domer at FTS 857-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IR27
5/10