

REGIONAL DIRECTOR
DEPUTY DIRECTOR
ASSISTANT TO DIRECTOR
DIRECTOR, RRPI
DIRECTOR, EPOS
DIRECTOR, ENF/INV
DIRECTOR, ETI
PUBLIC AFFAIRS OFFICER



PTP-QC-81-119
Turkey Point Plant
July 13, 1981

TO: Mr. J. P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Atlanta, Georgia 30303

FROM: Mr. J. K. Hays, Plant Manager - Nuclear
Turkey Point Plant - DPR 31 and 41
Florida Power and Light Company
Miami, Florida




SUBJECT: MEMO FOR FACSIMILE TRANSMISSION TO CONFIRM
REPORTABLE OCCURRENCE 250-81-13

This memo confirms our telephone notification of the subject prompt notification reportable occurrence made Friday, July 10, 1981, to your Duty Officer, Mr. I. Villalva as follows:

OCCURRENCE - On Friday, July 10, 1981, a relatively small void discovered in the concrete immediately below the equipment hatch barrel was determined to be reportable in accordance with technical specification 6.9.2.a.(9). This void was found in the course of making some alterations at the equipment hatch to facilitate handling equipment and large components during the steam generator repair effort.

CORRECTIVE ACTION - Unit 3 is presently defueled and undergoing inservice inspection of the reactor vessel. Prior to restarting the unit an engineering evaluation (currently in progress) and any necessary repairs will be completed. A plan for inspection of the same area on Unit 4 is pending completion of the engineering evaluation.


J. K. Hays
Plant Manager - Nuclear

JKH:cm

IE22
5/10

8107310399 810713
PDR ADOCK 05000250
S PDR