

**CP&L**

OFFICIAL COPY

Carolina Power &amp; Light Company

~~SEP 16 1980 10:37~~

Company Correspondence

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, N.C. 28461

September 10, 1980

FILE: B09-13513

SERIAL: BSEP/80-1481

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 & 2  
LICENSE NOS. DPR-71 AND DPR-62  
DOCKET NOS. 50-325 AND 50-324CONFIRMATION FASCIMILE OF AN IMMEDIATELY REPORTABLE EVENT

Dear Mr. O'Reilly:

This fascimile confirms the conversation between Art Johnson, of your office and Robert Poulk, Regulatory Compliance Specialist, at 0920 on September 6, 1980 concerning an immediately reportable event per IE Bulletin 80-17 at the Brunswick Steam Electric Plant.

Normal surveillance revealed the Unit No. 1 HPCI System steam supply inlet drain valves were leaking past their seats to the Reactor Building equipment drain tank.

The HPCI System is under clearance for repair of these valves which is expected to take several days.

Very truly yours,

A. C. Tollison, Jr., General Manager  
Brunswick Steam Electric Plant

RMP/jal

cc: Mr. D. L. Bensinger  
Mr. C. S. Bohanan  
Mr. B. J. Furr  
Mr. J. M. Johnson  
Mr. S. McManus8108030098 800910  
PDR ADDCH 05000324  
S PDRIE22  
5/10

OFFICIAL COPY