

OFFICIAL COPY

400 Chestnut Street Tower II

50-518

July 1, 1981

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT UNITS A1, B2, AND B1 - REPORTABLE  
DEFICIENCY - RPV SHIELD WALL WELD DEFICIENCIES (NCR'S HNP-A-087,  
HNP-A-108, HNP-A-109, HNP-A-115, AND SX-19)

Initial notification of the subject deficiency was made to NRC-OIE,  
Region II Inspector R. W. Wright on February 15, 1980. The final  
report was submitted on June 2, 1981. As discussed with Pete Taylor  
of your staff on June 18, 1981, TVA has failed to complete  
corrective actions by the committed date of June 15, 1981. We now  
plan on completing all corrective actions on or before August 16,  
1981. If you have any questions, please call Jim Domer at FTS  
857-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

IE27  
5/10