

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 S C N E E 1 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CONT
01 REPORT SOURCE L 6 0 5 0 0 0 2 6 9 7 0 7 1 5 8 1 3 0 7 2 3 8 1 9
7 8 9 DOCKET NUMBER 58 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During the visual examination of the Oconee 1 reactor vessel internal
03 components, several unexpected conditions were observed. Four thermal
04 shield bolts were missing as was one guide block. Due to the function
05 served by the thermal shield and the manner in which the core internals are
06 structured, this event has no safety significance.
07
08

09 SYSTEM CODE R A 11 CAUSE CODE X 12 CAUSE SUBCODE X 13 COMPONENT CODE X X X X X X X 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 LER/RO REPORT NUMBER 8 1 1 1 21 22 SEQUENTIAL REPORT NO. 0 1 1 24 25 OCCURRENCE CODE 0 1 27 28 REPORT TYPE T 30 REVISION NO. 0 32
18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN X 18 FUTURE ACTION X 19 EFFECT ON PLANT C 20 SHUTDOWN METHOD Z 21 HOURS 2 4 0 0 22 ATTACHMENT SUBMITTED Y 23 NPROG FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER B 0 1 1 5 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The apparent cause has not been determined. A program has been defined
11 to determine the cause and to effect repairs.
12
13
14

15 FACILITY STATUS H 28 % POWER 0 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 10-YR (S) 32 DISCOVERY DESCRIPTION
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 RELEASED OR RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION Repair effort still in progress - no estimate available
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 LOSS OF OR DAMAGE TO FACILITY TYPE D 42 DESCRIPTION See details attached. 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45 NRC USE ONLY
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER R. L. Gill

PHONE: (704) 373-5826

8108030156 810724
PDR ADDCK 05000269
S PDR