

0	1	A L J M F 1												2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5																																																																	
3		9												14												15												25												26												30												57												58											
		LICENSEE CODE																								LICENSE NUMBER																								LICENSE TYPE												CAT																																			

  

REPORT SOURCE		L	6	0	5	0	0	0	3	4	8	7	0	6	0	2	8	1	3	0	7	0	1	8	1	9																																			
		60	61	68												69	74												75												80																				
														DOCKET NUMBER																								EVENT DATE												REPORT DATE											

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | At 1406 on 6/2/81, while performing FNP-1-STP-28.1 (Diesel Generator 1C (2C) Operability  
03 | Test), a sequencer (BlH) associated with diesel generator 1C failed to meet the time re-  
04 | quirement for picking up step 2. (Note: At this time D.G. 1B had been taken out of  
05 | service in order to perform maintenance). Tech. Spec. 3.8.1.1, in part, requires the  
06 | BlH sequencer to be operable. Tech. Spec. 3.8.1.1 action statement requirements were  
07 | met. A similar occurrence was reported in Unit 1 LER 80-052/03L-0. This LER is  
08 | applicable to both Units 1 and 2 of FNP.

SYSTEM CODE E E (11)		CAUSE CODE X (12)		CAUSE SUBCODE Z (13)		COMPONENT CODE R E L A Y X (14)				COMP. SUBCODE M (15)		VALVE SUBCODE Z (16)	
LER/RO REPORT NUMBER 8 1 (17)		EVENT YEAR 8 1 (21) 22		SEQUENTIAL REPORT NO. 0 4 3 (24) 25		OCCURRENCE CODE 0 3 (28) 29		REPORT TYPE L (30)		REVISION NO. 0 (32)			
ACTION TAKEN E (18)		FUTURE ACTION Z (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22)		ATTACHMENT SUBMITTED N (23)		NPRD-4 FORM SUB. N (24)	
PRIME COMP. SUPPLIER A (25)		COMPONENT MANUFACTURER A 1 0 9 (26)											

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This incident is attributable to setpoint drift. The agastat timer was adjusted and the

1 1 | BlH sequencer was returned to service at 1845 on 6/2/81.

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	1	0	0	NA	B	Performance of STP						
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
1	6	Z	Z	NA		NA			NA					
PERSONNEL EXPOSURES			PERSONNEL INJURIES			LOSS OF OR DAMAGE TO FACILITY			PUBLICITY					
NUMBER			NUMBER			TYPE			DESCRIPTION					
1	7	0	0	0	0	Z	NA			8108030165 810701				
DESCRIPTION			DESCRIPTION			DESCRIPTION			PDR AD0CK 05000348					
1	3	0	0	0	0	Z	NA			PDR				
TYPE			TYPE			TYPE			NRC USE ONLY					
1	9	Z	NA			NA			68 69					
ISSUED			DESCRIPTION			DESCRIPTION			DESCRIPTION					
2	0	N	NA			NA			NA					

NAME OF PREPARER W. G. Hairston, III

PHONE: (202) 899-5156