

TENNESSEE VALLEY AUTHORITY
1750 Chestnut Street Tower II

July 24, 1981

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE
REPORT BFRO-50-260/81023 REVISION 1

The enclosed report is a supplement to my letter to you dated June 9, 1981,
concerning switches PS-1-81A and B and PS-1-91A and B which were found to be
an average of 4.2 percent above the limit of Technical Specification 3.1.A.
This report is submitted in accordance with Browns Ferry unit 2
Technical Specification 6.7.2.a(5).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

A handwritten signature in dark ink, appearing to read "H. J. Green".

H. J. Green
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

IE22
31/1