

1750 Chestnut Street Tower II

21 JUL 1981 10:50  
July 10, 1981

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET  
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE  
REPORT BFR0-50-296/81028

The enclosed report provides details concerning 3-A reactor recirculation  
pump which tripped because its motor-generator set tripped. This  
report is submitted in accordance with Browns Ferry unit 3 Technical  
Specification 6.7.2.b.2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Green*  
J. J. Green  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

IER2  
5/11