

## DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242  
2WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

July 24, 1981

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303


Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369



Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/81-104. This report concerns Technical Specification 3.3.3.9; "The radioactive gaseous effluent monitoring instrumentation channels shown in Table 3.3-13 shall be operable with their alarm/trip setpoints set to ensure that the limits of Specification 3.11.2.1 are not exceeded." This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

  
William O. Parker, Jr.PBN:pw  
Attachment

cc: Director  
Office of Management & Program Analysis  
U.S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
Post Office Box 10412  
Palo Alto, CA 94303

Ms. M. J. Graham  
Resident Inspector - NRC  
McGuire Nuclear Station

IE22  
5/11

8108030216 810724  
PDR ADGCK 05000369  
S PDR