

## TENNESSEE VALLEY AUTHORITY

OFFICIAL COPY

CHATTANOOGA, TENNESSEE 37401

USNRC REGION 7

1750 Chestnut Street Tower II

ATLANTA, GEORGIA

June 29, 1981

31 JUL 7 A7:54

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE  
REPORT SQRO-50-327/81064

The enclosed report provides details concerning the inoperability of lower containment radiation monitor 1-RM-90-106 when the sample pump motor tripped on overcurrent. This event caused Sequoyah unit 1 to enter action statement 19 of limiting condition for operation 3.3.3.1 and the action statement for limiting condition for operation 3.4.6.1 and is reported under Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Green*  
J. A. Green

Director of Nuclear Power



Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)

Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavalley  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

NRC Inspector, Sequoyah

IE22  
5/11

8108030222 810629  
PDR ADOCK 05000327  
S PDR

An Equal Opportunity Employer