

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

OFFICIAL COPY

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

April 17, 1981

TELEPHONE: AREA 704  
373-4083

81-039-036

Mr. J. P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-569/81-33. This report concerns improper gauge of stainless steel used for ductwork in the containment purge system isolation valves. This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

William O. Parker, Jr.

RWO/mwk  
Attachment

cc: Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Bill Lavalee  
Nuclear Safety Analysis Center  
Post Office Box 10412  
Palo Alto, California 94303

IE22  
5/11