

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:										PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION									
<div> <div>01</div> <div>N C M G S I</div> <div>200-000000-000</div> <div>3411111</div> <div>4</div> <div>5</div> </div>										<div> <div>7</div> <div>8</div> <div>9</div> <div>10</div> <div>11</div> <div>12</div> <div>13</div> <div>14</div> <div>15</div> <div>16</div> <div>17</div> <div>18</div> <div>19</div> <div>20</div> <div>21</div> <div>22</div> <div>23</div> <div>24</div> <div>25</div> <div>26</div> <div>27</div> <div>28</div> <div>29</div> <div>30</div> <div>31</div> <div>32</div> <div>33</div> <div>34</div> <div>35</div> <div>36</div> <div>37</div> <div>38</div> <div>39</div> <div>40</div> <div>41</div> <div>42</div> <div>43</div> <div>44</div> <div>45</div> <div>46</div> <div>47</div> <div>48</div> <div>49</div> <div>50</div> <div>51</div> <div>52</div> <div>53</div> <div>54</div> <div>55</div> <div>56</div> <div>57</div> <div>58</div> <div>59</div> <div>60</div> <div>61</div> <div>62</div> <div>63</div> <div>64</div> <div>65</div> <div>66</div> <div>67</div> <div>68</div> <div>69</div> <div>70</div> <div>71</div> <div>72</div> <div>73</div> <div>74</div> <div>75</div> <div>76</div> <div>77</div> <div>78</div> <div>79</div> <div>80</div> </div>									
<div> <div>01</div> <div>REPORT SOURCE</div> <div>L</div> <div>6</div> <div>0</div> <div>5</div> <div>0</div> <div>0</div> <div>0</div> <div>0</div> <div>3</div> <div>6</div> <div>9</div> <div>7</div> <div>0</div> <div>6</div> <div>1</div> <div>2</div> <div>8</div> <div>1</div> <div>8</div> <div>0</div> <div>17</div> <div>0</div> <div>8</div> <div>8</div> <div>1</div> <div>9</div> </div>										<div> <div>02</div> <div>EVENT DESCRIPTION AND PROBABLE CONSEQUENCES</div> <div>10</div> </div>									
<div> <div>02</div> <div>While in Mode 5, routine surveillance discovered that the quantity of fire de-</div> </div>										<div> <div>03</div> <div>tection equipment installed in 5 fire zones did not comply with the minimum re-</div> </div>									
<div> <div>04</div> <div>quired in Table 3.3-11 of the Tech. Specs. and subsequently were declared in-</div> </div>										<div> <div>05</div> <div>operable. This was a violation of TS 3.3.3.7 and is reportable per TS 6.9.1.13B.</div> </div>									
<div> <div>06</div> <div>In addition to establishing an hourly firewatch, it was determined that the type</div> </div>										<div> <div>07</div> <div>and quantity of fire protection equipment installed in each area met the appro-</div> </div>									
<div> <div>08</div> <div>priate standards and thus the health and safety of the public were not affected.</div> </div>										<div> <div>09</div> <div>SYSTEM CODE</div> <div>A</div> <div>B</div> <div>11</div> <div>CAUSE CODE</div> <div>X</div> <div>12</div> <div>CAUSE SUBCODE</div> <div>Z</div> <div>13</div> <div>COMPONENT CODE</div> <div>Z</div> <div>Z</div> <div>Z</div> <div>Z</div> <div>Z</div> <div>Z</div> <div>14</div> <div>COMP. SUBCODE</div> <div>Z</div> <div>15</div> <div>VALVE SUBCODE</div> <div>Z</div> <div>16</div> </div>									
<div> <div>17</div> <div>LER/RO REPORT NUMBER</div> <div>8</div> <div>1</div> <div>21</div> <div>EVENT YEAR</div> <div>8</div> <div>1</div> <div>22</div> <div>SEQUENTIAL REPORT NO.</div> <div>0</div> <div>1</div> <div>9</div> <div>7</div> <div>24</div> <div>OCCURRENCE CODE</div> <div>0</div> <div>3</div> <div>28</div> <div>REPORT TYPE</div> <div>L</div> <div>30</div> <div>REVISION NO.</div> <div>0</div> <div>32</div> </div>										<div> <div>18</div> <div>ACTION TAKEN</div> <div>X</div> <div>18</div> <div>FUTURE ACTION</div> <div>Z</div> <div>19</div> <div>EFFECT ON PLANT</div> <div>Z</div> <div>20</div> <div>SHUTDOWN METHOD</div> <div>Z</div> <div>21</div> <div>HOURS</div> <div>0</div> <div>0</div> <div>0</div> <div>0</div> <div>22</div> <div>ATTACHMENT SUBMITTED</div> <div>Y</div> <div>23</div> <div>NPRA FORM SUB.</div> <div>N</div> <div>24</div> <div>PRIME COMP. SUPPLIER</div> <div>Z</div> <div>25</div> <div>COMPONENT MANUFACTURER</div> <div>Z</div> <div>9</div> <div>9</div> <div>9</div> <div>26</div> </div>									
<div> <div>10</div> <div>CAUSE DESCRIPTION AND CORRECTIVE ACTIONS</div> <div>27</div> </div>										<div> <div>11</div> <div>The discrepancy from the Tech. Specs. in one fire zone was the result of a</div> </div>									
<div> <div>12</div> <div>typographical error in Table 3.3-11. The other 4 zone's discrepancies were due</div> </div>										<div> <div>13</div> <div>to incorrect blueprints, the reason for which is unknown. Hourly firewatches</div> </div>									
<div> <div>14</div> <div>were established, and it was determined that the other zone's fire protection</div> </div>										<div> <div>15</div> <div>equipment was adequate. NRC approval of the existing equipment and TS changes</div> </div>									
<div> <div>16</div> <div>were requested and received.</div> </div>										<div> <div>17</div> <div>FACILITY STATUS</div> <div>X</div> <div>28</div> <div>% POWER</div> <div>0</div> <div>0</div> <div>0</div> <div>29</div> <div>OTHER STATUS</div> <div>Mode 5</div> <div>30</div> <div>METHOD OF DISCOVERY</div> <div>B</div> <div>31</div> <div>DISCOVERY DESCRIPTION</div> <div>Routine Surveillance</div> <div>32</div> </div>									
<div> <div>18</div> <div>ACTIVITY RELEASED</div> <div>Z</div> <div>33</div> <div>CONTENT</div> <div>Z</div> <div>34</div> <div>AMOUNT OF ACTIVITY</div> <div>NA</div> <div>35</div> <div>LOCATION OF RELEASE</div> <div>NA</div> <div>36</div> </div>										<div> <div>19</div> <div>PERSONNEL EXPOSURES</div> <div>0</div> <div>0</div> <div>0</div> <div>37</div> <div>TYPE</div> <div>Z</div> <div>38</div> <div>DESCRIPTION</div> <div>NA</div> <div>39</div> </div>									
<div> <div>20</div> <div>PERSONNEL INJURIES</div> <div>0</div> <div>0</div> <div>0</div> <div>40</div> <div>DESCRIPTION</div> <div>NA</div> <div>41</div> </div>										<div> <div>21</div> <div>LOSS OF OR DAMAGE TO FACILITY</div> <div>Z</div> <div>42</div> <div>DESCRIPTION</div> <div>NA</div> <div>43</div> </div>									
<div> <div>22</div> <div>PUBLICITY ISSUED</div> <div>N</div> <div>44</div> <div>DESCRIPTION</div> <div>NA</div> <div>45</div> </div>										<div> <div>23</div> <div>NRC USE ONLY</div> </div>									
<div> <div>24</div> <div>NAME OF PREPARER</div> <div>Phillip B. Nardoci</div> </div>										<div> <div>25</div> <div>PHONE:</div> <div>(704) 373-7432</div> </div>									

8108030267 810708
PDR ADDCK 05000369
S PDR