

OFFICIAL COPY

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461

June 25, 1981

FILE: B09-13516.2
SERIAL: BSEP/81-1271



Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 & 2
LICENSE NOS. DPR-71 AND DPR-62
DOCKET NOS. 50-325 AND 50-324
CONFIRMATION FACSIMILE FOR AN IMMEDIATELY REPORTABLE EVENT

Dear Mr. O'Reilly:

This confirms conversation between Mr. C. S. Bohanan, Principal Regulatory Specialist, and Mr. Ross Butcher of your office at 0850 on June 25, 1981, concerning an immediately reportable event.

On June 24, 1981, Brunswick Steam Electric Plant received notification from United Engineers and Constructors, Inc., that an analysis indicated that 38 CRD gang pipe supports (17 for Unit No. 1 and 21 for Unit No. 2) would fail in the as built condition during a DESIGN SEISMIC EVENT. These supports have been modified and reanalyzed and are now of sufficient strength to meet all designed requirements. This event is being reported under Technical Specification 6.9.1.8i and will be addressed under LER 2-81-56.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/gvc

cc: Mr. R. A. Hartfield
Mr. V. Stello, Jr.

IE29
5/10

8108030293 810625
PDR ADDCK 05000324
S PDR