

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 S C N E E 3 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CONF
0 1 REPORT SOURCE L 8 0 5 0 0 0 2 8 7 7 0 5 2 8 8 1 8 0 6 2 6 8 1 9
7 8 9 DOCKET NUMBER 58 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 On May 28, 1981, a 1-inch breach in a 3-hour fire barrier was discovered in the
0 3 floor of the Unit 3 Control Room just outside of the Shift Supervisor's office.
0 4 Due to the low combustibility of materials, the small size of the breach, and the
0 5 smoke detectors located on both sides of the breach, the possibility of a fire
0 6 spreading was very low. Additionally, the Control Room is continuously manned.
0 7 Therefore, this incident was of no significance with respect to safe operation,
0 8 and the health and safety of the public were not affected.

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
7 8 9 A B 11 X 12 Z 13 X X X X X X 14 Z 15 Z 16

17 LER/RO REPORT NUMBER 8 1 1 0 1 3 0 3 L 0
7 8 9 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM 308 PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
B 18 Z 19 Z 20 Z 21 0 0 0 0 Y 22 N 24 I 25 X 9 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The cause of this incident cannot be clearly defined because the breach had been
1 1 covered since construction of the Unit 3 Control Room. The breach was a
1 2 threaded pipe sleeve. The threads were chased with a 1-inch pipe die to clean
1 3 them. Two 1-inch pipe plugs were then installed to seal the barrier. The
1 4 penetration will be placed on inspection procedure MP/O/A/3020/05.

1 5 FACILITY STATUS 1 0 0 1 NA METHOD OF DISCOVERY A 31 Operator Observation
7 8 9 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
7 8 9 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA
7 8 9 37 38 39 40 41 42 43 44 45 46 47

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA
7 8 9 40 41 42 43 44 45 46 47

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43 NA
7 8 9 42 43 44 45 46 47

2 0 PUBLICITY ISSUED DESCRIPTION 45 NA
7 8 9 44 45 46 47

NAME OF PREPARER J. L. Jones PHONE: (704) 373-8197