

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE BOX 764

COLUMBIA, SOUTH CAROLINA 29218

OFFICIAL COPY

T. C. NICHOLS, JR.  
VICE PRESIDENT AND GROUP EXECUTIVE  
NUCLEAR OPERATIONS

June 29, 1981

7 48.03



Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II, Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Subject: Virgil C. Summer Nuclear Station  
Docket No. 50/395  
Potential Substantial Safety Hazard  
Final Report

Dear Mr. O'Reilly:

On January 6, 1981, Mr. Bob McFarland of NRC Region II was notified of a potential substantial safety hazard on the subject: Cracked HFA Relay Coil Spools. On February 13, 1981, an interim report was sent on the above item.

We were advised of the possibility of the cracked Relay Coil Spools by General Elect. letter dated December 19, 1980. We obtained a list of safety related HFA relays and their locations. Nuclear Operations Electrical Maintenance completed a search for defective HFA relays and none of the potentially defective relay coils in the plant equipment or in spare parts were discovered.

Therefore, substantial safety hazard on this subject does not exist. This is considered a final report on the matter.

Very truly yours,

*[Signature]*  
for T. C. Nichols, Jr.

JAW:TCN:1kb

cc: V. C. Summer	H. N. Cyrus
G. H. Fischer	J. B. Knotts
T. C. Nichols, Jr.	J. L. Skolds
E. H. Crews, Jr.	B. A. Bursey
O. W. Dixon, Jr.	O. S. Bradham
C. A. Price	Document Management Branch
D. A. Nauman	I&E
W. A. Williams, Jr.	ISEG
R. B. Clary	NPCF
A. R. Koon	File
A. A. Smith	
J. Ruoff	

IE27  
51/0