

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

0	1
---	---

REPORT SOURCE

60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80				
	6	0	5	0	0	0	3	1	1	7	0	6	1	2	8	1	8	0	7	1	0	8	1	9

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Pressurizer Overpressure Protection System (POPS) channel 1 and 2 had to be declared

0 3 | inoperable on June 12 and 18, 1981, due to 2PR47 and 2PR2 leakage to the

0 4 | pressurizer relief tank. Isolation of these valves caused (POPS) channels 1 and 2

0 5 | to be inoperable with the Reactor Coolant System temperature of less than 312°F in

0 6 | accordance with technical specification 3.4.9.3.b.

0	7	
0	8	

SYSTEM CODE C J 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE V A L V X 14		COMP SUBCODE D 15		VALVE SUBCODE B 16	
LER RO REPORT NUMBER 8 1 17		EVENT YEAR 8 1 21 22		SEQUENTIAL REPORT NO. 0 4 3 24 26		OCCURRENCE CODE / 27		REPORT TYPE L 30		REVISION NO. 0 32	
ACTION TAKEN Z 18		FUTURE ACTION A 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22		ATTACHMENT SUBMITTED Y 23	
NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER L 25		COMPONENT MANUFACTURER C 6 3 5 26							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Valves 2PR2 and 2PR47 will be inspected and repaired at the next refueling outage.

1 1 | A supplemental report will be submitted upon repair completion.

1 2 |

1 3 |

1 4 |

8 9
FACILITY STATUS % POWER OTHER STATUS (30)
1 5 D (28) 0 0 0 (29) N/A
7 8 9 10 12 13 44
ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 2 (33) Z (34) NA
7 8 9 10 11 44
METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
A (31) Operator Observation
45 46 80
LOCATION OF RELEASE (36)
NA
45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	2	38	NA	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)

1 9 Z (42) NA

7 8 9 10 80

PUBLICITY								NRC USE ONLY															
ISSUED		DESCRIPTION																					
2	0	N	(44)	NA																			
8		9		10		68						69 80											

J. J. Espey

PHONE: 609-935-0998