

400 Chestnut Street Tower II

July 7, 1981

HTRD-50-518/81-10

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT UNIT A1 - REPORTABLE DEFICIENCY - UNFUSED
MATERIAL IN DRYWELL VENT STRUCTURE FRAME NO. 7 CLOSURE PLATE WELD -
HTRD-50-518/81-10

The subject deficiency was initially reported to NRC-OIE, Region II, Inspector Pete Taylor on March 30, 1981 as NCR HNP-A-136. The final report was submitted on June 2, 1981. As discussed with Inspector Taylor on June 29, 1981, TVA was unable to complete corrective actions on or before the July 1, 1981 commitment date as stated in our final response. TVA now anticipates completing corrective actions on or before August 1, 1981. If you have any questions, please call Jim Domer at FTS 857-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IEZ?
9/1/81