

1750 Chestnut Street Tower II

OFFICIAL COPY

July 24, 1981

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT, UNIT 2 - DOCKET
NO. 50-260 - FACILITY OPERATING LICENSE DFR-52 - REPORTABLE OCCURRENCE
REPORT BFRO-50-260/81028 REVISION 1

The enclosed report is a supplement to my letter to you dated June 25, 1981, concerning reactor high-pressure switches PS 68-93 switch 2 and PS 68-94 switch 2 controlling shutdown cooling valves of the residual heat removal system which were found to be above limits of Technical Specification 3.2.A. This report is submitted in accordance with Browns Ferry unit 2 Technical Specification 6.7.2.A(5).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
H. J. Green
Director of Nuclear Power.

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)

Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

*IF22
5/1*