

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N C M G S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T  
 0 1  
 7 8

REPORT SOURCE 1 6 0 1 5 1 0 0 0 3 6 1 9 7 0 4 2 8 8 1 1 8 0 5 2 8 8 1 1 9  
 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  
 0 2 While in Mode 5, initial fuel loading, and after completing a periodic  
 0 3 stroke test, RHR isolation valve INDB would not reopen. This is in  
 0 4 violation of Technical Specification 2.4.1.4 and is reportable per Technical  
 0 5 Specification 6.9.1.13(b). Since the Control Room operators were aware of  
 0 6 the testing of the valve, its inoperability did not affect the safe operation  
 0 7 of the plant or the health and safety of the public.  
 0 8  
 0 9

SYSTEM CODE 11 C F 12 CAUSE CODE X 13 CAUSE SUBCODE X 14 COMPONENT CODE V A L V E X 15 COMP. SUBCODE E 16 VALVE SUBCODE D 17  
 18 LEAD REPORT NUMBER 19 EVENT YEAR 20 SEQUENTIAL REPORTING NO. 21 OCCURRENCE CODE 22 REPORT TYPE 23 REVISION NO.  
 24 ACTION TAKEN 25 FUTURE ACTION 26 EFFECT ON PLANT 27 SHUTDOWN METHOD 28 HOURS 29 ATTACHMENT SUBMITTED 30 NPRO-4 FORM SUB. 31 PRIME COMP. SUPPLIER 32 COMPONENT MANUFACTURER  
 33 E 34 Z 35 Z 36 Z 37 0 0 0 0 38 Y 39 N 40 L 41 W 42 Q 43 3 44 0 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  
 1 0 The RHR isolation valve would not reopen after its stroke test. The cause  
 1 1 of this failure could not be readily determined. The limit switches were  
 1 2 adjusted and when the valve was cycled it was functioning properly.  
 1 3  
 1 4

FACILITY STATUS 28 X 29 % POWER 0 0 0 0 30 OTHER STATUS Mode 5 31 METHOD OF DISCOVERY A 32 DISCOVERY DESCRIPTION Personnel Observation  
 33 ACTIVITY CONTENT 34 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE NA 37  
 38 PERSONNEL EXPOSURES 39 NUMBER 0 0 0 40 TYPE Z 41 DESCRIPTION NA  
 42 PERSONNEL INJURIES 43 NUMBER 0 0 0 44 DESCRIPTION NA  
 45 LOSS OF OR DAMAGE TO FACILITY 46 TYPE Z 47 DESCRIPTION NA  
 48 PUBLICITY 49 ISSUED N 50 DESCRIPTION NA  
 51 NAME OF PREPARER R. W. Ouellette 52 PHONE: (704) 373-7530