

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

July 23, 1981

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-21 -RIT: JPO 50-518,
-519, -520, -521, -553, -554 - HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS

On January 5 and May 27, 1981 TVA submitted the first and second interim responses to the subject bulletin. This letter constitutes TVA's final response to your November 6, 1980 letter to H. G. Parris.

Final responses from GE and valve vendors indicate that no safety-related valves purchased for Hartsville or Phipps Bend Nuclear Plants (for STRIDE or BOP) have parts made by Malcolm Foundry Company, Inc. If you have any questions, please call Jim Domer at FTS 857-2014.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Division of Reactor Operations Inspection
Washington, DC 20555

IE11
s
1/0

8108040136 810720
PDR ADOCK 05000518
Q PDR