

# LICEN

CONTROL BLOCK:

PLEASE PROVIDE ALL REQUIRED INFORMATION

01 T N S N P 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
 7 8 9 14 15 25 26 30 37 CAT 50

CONT  
 01 REPORT SOURCE L 6 0 5 0 0 0 3 2 7 7 0 6 2 7 8 1 8 0 7 2 4 8 1 9  
 7 8 50 51 DOCKET NUMBER 56 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Unit 1 in mode 2 with RCS temperature and pressure at 547°F and 2235 PSIG. The 1A-A  
 03 safety injection pump was declared inoperable when water was discovered in the lube oil.  
 04 This event required entry into LCO 3.5.2. There was no effect upon public health or  
 05 safety. Previous Occurrences - 1 (Ref SQRO-50-327/81033)

06  
 07  
 08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
 C J 11 X 12 Z 13 P U M P X X 14 B 15 Z 16  
 9 10 11 12 13 18 19 20  
 17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
 8 1 0 7 6 0 3 L 0  
 21 22 23 24 26 27 28 29 30 31 32  
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
 X 18 X 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 P 0 2 6  
 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Water in oil is caused by condensation buildup. The oil was changed within 3 hours.  
 11 The lube oil cooler was leak checked and no leaks were found. A preventative maintenance  
 12 program has been implemented to sample the oil monthly to verify rate of water  
 13 buildup and to verify cause. A freon leak check will be performed on the lube oil  
 14 cooler.

15 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
 C 26 0 0 0 29 NA B 31 Operations Personnel Observation  
 7 8 9 10 12 13 44 45 46 80  
 16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
 Z 33 Z 34 NA NA  
 7 8 9 10 11 44 45 80  
 17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (30)  
 0 0 0 37 Z 38 NA  
 7 8 9 11 12 13 80  
 18 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  
 0 0 0 40 NA  
 7 8 9 11 12 80  
 19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)  
 Z 42 NA  
 7 8 9 10 80  
 20 PUBLICITY ISSUED DESCRIPTION (45)  
 N 44 NA  
 7 8 9 10 80  
 8108040281 810724  
 PDR ADOCK 05000327  
 S PDR  
 NRC USE ONLY  
 7 8 9 10 58 59

Name of Preparer: Glenn B. Kirk/Mike R. Harding

Phone: (615) 842-8317