

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
1750 Chestnut Street Tower II

USNRC REGION 7
ATLANTA, GEORGIA

July 27, 1981

31 JUL 30 A10: 5~

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/81032 REVISION 1

The enclosed report is a supplement to my letter to you dated June 26,
1981, concerning switches PS 68-93 and -94 which were out of the limits
of Technical Specifications 3.2.A and 3.2.B. This report is submitted
in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.A(5).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Loney
H. J. Green
Director of Nuclear Power



Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

IE22
5/11

8108100256 810727
PDR ADOCK 05000259
S PDR