

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

REPORT SOURCE L 5 0 5 0 - 0 3 2 4 7 0 7 0 4 8 1 8 0 7 2 8 8 1 9

DOCKET NUMBER 68 69

EVENT DATE 74

REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal surveillance it was discovered that control rod 14-27 did not have
0 3 | full-in position indication lights lit while fully inserted. All other position indi-
0 4 | cations, including full-out, for the rod were operable. The rod was then bypassed in
0 5 | the Rod Sequence Control System in accordance with technical specifications. This
0 6 | event did not affect the health or safety of the public.
G 7 | _____
0 8 | _____ Technical Specifications 3.1.3.7, 6.9.1.9b
7 8 9

0 9		SYSTEM CODE I B		CAUSE CODE E		CAUSE SUBCODE A		COMPONENT CODE Z Z Z Z Z Z						COMP. SUBCODE Z		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22		
LER-RO REPORT NUMBER		EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 6 2		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN X		FUTURE ACTION X			
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38		
SHUTDOWN METHOD Z		EFFECT ON PLANT Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. Y		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER G 0 8 0		CAUSE DESCRIPTION AND CORRECTIVE ACTIONS			
39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A failed reed switch located in the drywell caused this problem. It will be repaired
1 1 during a future outage. A failure of an individual reed switch does not constitute a
1 2 safety hazard and failures are expected on an occasional basis. These switch failures
1 3 will continue to be repaired as required and no design modifications are planned.

1 4
7 8 9

FACILITY STATUS (1) 5 (F) (28) % POWER (0) 6 9 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (A) (31) DISCOVERY DESCRIPTION (32) Operator Surveillance

ACTIVITY CONTENT (1) 6 (Z) (33) (Z) (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES NUMBER (1) 7 (0) 0 0 (37) TYPE (Z) (38) DESCRIPTION (39) NA

PERSONNEL INJURIES NUMBER (1) 8 (0) 0 0 (40) DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY TYPE (1) 9 (Z) (42) DESCRIPTION (43) NA

PUBLICITY ISSUED (2) 0 (N) (44) DESCRIPTION (45) NA

8108100312 810728
PDR ADDCK 05000324
S PDR ARER - M. J. Pastva, Jr.
PHONE 919-457-9521