

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I A D A C 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 56

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 3 1 7 0 7 0 1 8 1 9 0 7 3 1 8 1 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During surveillance testing Containment Atmosphere Monitoring System (CA
0 3 MS) A was found to be operating without a sample point having been resel
0 4 ected. CAMS B was inoperative due to surveillance testing. Containment
0 5 atmosphere was therefore not being monitored. Tech. Spec. 3.6.C lists CA
0 6 MS operability requirements. There has been one previous similar occurre
0 7 nce with the Containment Atmosphere Monitoring System (See RO 81-026).
0 8
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

0 9 SYSTEM CODE CAUSE CODE CAUSE SUB CODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
B B 11 A 12 A 13 Z Z Z Z Z Z 14 Z 15 Z 16
17 LER/RO REPORT NUMBER 18 1 19 0 20 9 21 0 22 3 23 L 24 0 25 0
26 ACTION TAKEN 27 FUTURE ACTION 28 EFFECT ON PLAN 29 SHUTDOWN METHOD 30 HOURS 31 ATTACHMENT SUBMITTED 32 NPRO-4 FORM SUB. 33 PRIME COMP. SUPPLIER 34 COMPONENT MANUFACTURER
35 H 36 H 37 Z 38 Z 39 0 40 0 41 N 42 N 43 Z 44 Z 45 9 46 9 47 9 48 9 49 9 50 9
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Personnel error. Control room operators did not follow procedures closel
1 1 y. Problem corrected within 10 minutes by operator reselection of a samp
1 2 le point for CAMS A. Appropriate personnel are being reinstructed on CAM
1 3 S operation. Sample point selection verification has been added to shift
1 4 instrument check list. A design review has been initiated.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

1 5 FACILITY STATUS 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
E 28 0 6 3 29 NA 30 METHOD OF DISCOVERY 31 B 32 Operator Observation 33
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
ACTIVITY CONTENT 34 Z 35 Z 36 NA 37 AMOUNT OF ACTIVITY 38 NA 39 LOCATION OF RELEASE 40

1 7 PERSONNEL EXPOSURES 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
0 0 0 37 Z 38 NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

1 4 PERSONNEL INJURIES 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
0 0 0 40 NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

1 3 LOSS OF OR DAMAGE TO FACILITY 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
7 42 NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

2 0 PUBLICITY 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
N 44 NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40