

DMB/LEK



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901



July 29, 1981

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

This is to confirm our verbal report to Mr. E.R. Swanson, NRC Region III Inspector, on July 29, 1981, at 1245 hours at which time we reported that we have a shim plate and some support shims missing from the #12 Reactor Coolant Pump.

A followup report will be submitted by August 11, 1981, as required by Technical Specification Section 6.9.1.8.i.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.S. Hunter
R.W. Jurgensen
R.F. Kroeger
K.J. Vehstedt
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
J.M. Hennigan
W. Lavallee EPRI
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

FE22
3
1/0

8108110406 810729
PDR ADOCK 05000315
S PDR

AUG 3 1981