

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242


WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

81 AUG 7 10:51  
August 4, 1981

TELEPHONE: AREA 704  
373-4083

Mr. J. P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303


Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369



Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/81-109. This report concerns Technical Specification 3.3.3.4, "The meteorological monitoring instrumentation channels shown in Table 3.3-8 shall be operable". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

  
William O. Parker, Jr.

PBN/krh  
Attachment

cc: Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Bill Lavalee  
Nuclear Safety Analysis Center  
Post Office Box 10412  
Palo Alto, California 94303

Ms. M. J. Graham  
Resident Inspector-NRC  
McGuire Nuclear Station

IE22  
5/11

8108130120 810804  
PDR ADOCK 05000369  
S PDR