

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
1750 Chestnut Street Tower II

August 7, 1981

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE  
REPORT BFRO-50-259/81041

The enclosed report provides details concerning the operate/test switch  
on continuous air monitor 1-RM-90-249 which would not operate while  
performing turbine building vent monitoring systems tests. This report  
is submitted in accordance with Browns Ferry unit 1 Technical  
Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Green*  
J. J. Green

Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)

Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavalley  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

8108130270 810807  
PDR ADOCK 05000259  
S PDR

*IF22*  
*5/11*