

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

DOI 10.1002/1522-2675(200107)23:7<1026::AID-HLCA1026>3.0.CO;2-6

ATTACHMENT TO LER #81-025/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

REPAIRED AND RETESTED WITH ACCEPTABLE LEAK RATES. AS THIRTEEN OF THE FOURTEEN NESW CHECK VALVES EXCEEDED GUIDELINE LEAKAGE DURING INITIAL TESTING, THESE VALVES WILL BE REPLACED WITH A DIAPHRAGM TYPE VALVE. AN ENGINEERING REVIEW IS IN PROGRESS FOR THE REMAINDER OF THESE VALVES.