

USNRC REGION II
ATLANTA, GEORGIA

01 AUG 19 11:04



August 17, 1981

PRN-LI-81-377

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-81-08
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: JULY 17, 1981

TECHNICAL SPECIFICATION 3.1.3.c
RCS LEAKAGE FROM PRESSURIZER SPRAY VALVE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,

A.D. Schmidt
for A.D. Schmidt
Vice President
Power Resources

IE22
S
1/1

PLP/ras

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

8108240093 810817
PDR ADOCK 05000251
S PDR