

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A L J M F 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

REPORT SOURCE L 5 0 5 0 0 0 3 6 4 7 0 7 1 7 8 1 2 0 8 1 8 8 1 9

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 At 0610 on 7-17-81, the instrumentation loop associated with steam flow transmitter

0 3 FT-474 was declared inoperable when the main control board steam flow indicator failed

0 4 high due to breakage of a transmitter vent pipe. Tech. spec. 3.3.1 and 3.3.2, in part,

0 5 require FT-474 to be operable. Tech. Spec. action statement requirements were met.

0 6 Health/safety of the public was not affected.

0 7

0 8

0 9

SYSTEM CODE T A 11 CAUSE CODE B 12 CAUSE SUBCODE A 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16

EVENT YEAR 8 1 17 SEQUENTIAL REPORT NO. 0 2 8 18 OCCURRENCE CODE 0 3 19 REPORT TYPE L 20 REVISION NO. 0 21

ACTION TAKEN A 22 FUTURE ACTION Z 23 EFFECT ON PLANT Z 24 SHUTDOWN METHOD Z 25 HOURS 0 0 0 0 26 ATTACHMENT SUBMITTED N 27 NPRO-4 FORM SUB. N 28 PRIME COMP. SUPPLIER Z 29 COMPONENT MANUFACTURER Z 9 9 9 30

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The use of an oversized valve in a sensing line which had higher than expected vibration

1 1 contributed to the fatigue failure of the line. Following installation of a lighter valve &

1 2 satisfactory completion of the surveillance test, the FT-474 instrumentation loop was returned

1 3 to service at 2210 on 7-19-81. All similar instrumentation vent lines were also inspected

1 4 and valves replaced. No such similar condition exists in Unit 1 since the heavier valve was

1 5 selected for use in Unit 2 because of an error on a vendor drawing.

FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY ISSUED Z 44 DESCRIPTION NA 45

2 0 8108240106 810819 PDR ADOCK 05000364 S PDR rer W. G. Hairston, III Phone: (205) 899-5156

NRC USE ONLY