

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 S C N E E 3 2 0 0 - 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 56

CONT 01

REPORT SOURCE L 5 0 5 0 0 0 2 8 7 7 0 7 2 0 8 1 8 0 8 1 7 8 1 9

DOCKET NUMBER 58 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On July 17, 1981 the 3-B LPI Pump was removed from service to correct a

03 high vibration problem on the motor. On July 20, 1981 while attempting to

04 perform an Engineered Safeguard (ES) periodic test, the 3-B LPI pump

05 failed to start. During the period of time that the 3-B LPI train was

06 inoperable, the "A" LPI train was operable. It is considered that this

07 incident did not represent a significant increase in risk to the health and

08 safety of the public.

SYSTEM CODE S F 11 CAUSE CODE A 12 CAUSE SUBCODE C 13 COMPONENT CODE M O T O R X 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16

EVENT YEAR 8 1 SEQUENTIAL REPORT NO. 0 1 5 OCCURRENCE CODE 0 1 REPORT TYPE T REVISION NO. 0

ACTION TAKEN X 18 FUTURE ACTION G 19 EFFECT ON PLANT B 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 ATTACHMENT SUBMITTED Y 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER L 25 COMPONENT MANUFACTURER W 1 2 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The Unit had to begin reducing power because the 24 hour limit permitted by

11 TS 3.3.2.b expired. The cause of the failure of the pump to start was

12 personnel error. The pump motor bearings were replaced. The person

13 involved has been counselled. The procedure will be revised to include

14 verifying the position of the spring charging motor switch.

FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY ISSUED DESCRIPTION NA 44

NAME OF PREPARER J. L. Jones PHONE: (704) 373-8197

NRC USE ONLY

8108240120 810817  
PDR ADOCK 05000287  
S PDR